## **Supporting document 2**

## Impact of slag addition on dry kiln operation


## 1. Outages of kiln system during 1-st half of 2008

Reason	Outage time, h	% of total outages time	Number of outages
Clogging of raw mill in cyclones	89.90	36.2	6
Mechanical part of kiln and cooler outage	52.55	21.1	2
Outage for cleaning of kiln main exhaust fan	36.40	14.6	4
Electrostatic precipitator electrical part repair	24.00	9.7	1
Electrical part of kiln outage	19.30	7.8	3
Outage for cooler cleaning	11.50	4.6	1
Other reasons	10.89	4.4	2
Power cut-outs	4.00	1.6	1

The data in the table above shows that the main outage time is clogging of the raw mill in cyclone system which results in i) production losses due to kiln stops, ii) additional labor and material cost.

## 2. Influence of chlorine and sulphur on clogging of materials

High content of sulphur compounds in slag lead to increase in clogging of raw mill in cyclone system (also see simplified diagram below).



Indirectly it also influences on the requirements to select the ferrous additives. For example, blast furnace throat dust, traditionally widely used before as ferrous additive, has high chlorine content and, in combination with slag, creates simultaneous high concentration of sulphur and chlorine, which causes plugging in cyclones. Due to this fact, the plant has to use another ferrous additive, the ill-conditioned fraction of iron ore, which has low chlorine content, but contains less ferrum, is harder to grind and has high content of low reactive crystalline quartz.

As a reference material explaining the reasons causing clogging or ring building, the two documents are included in supporting document 1 (SD1), the first is an article in "Cement-Calcium-Gypsum magazine" named "Reactions associated with the kiln gases. Cyclic processes of volatile substances, coatings, removal of rings", it has a summary of article in English at page 11. The second one is a report in Portland Cement Association R&D Information issue #1996 named "Kiln exit buid-ups: study of alkali and sulfur volatilization" by Presbury B. West. Below the title pages and abstract in English are presented.



## /IENT-KALK-GIPS

Dok.-Nr. 0-8162

Polycles A. G.

- 30-194

Literatur\_2

VERLAG UND SCHRIFTLEITUNG: BAUVERLAG OMBH, WIESBADEN, KLEINE WILHELMSTRASSE 7 TELEFON: SA.-NR. 39515, FERNSCHREIBER: 04-186792, HERAUSGEBER: MICHAEL SCHIRMER, WIESBADEN

### Reaktionen im Bereich der Ofengase\*)

Kreisläufe flüchtiger Stoffe, Ansätze, Beseitigen von Ringen

Reactions associated with the kiln guses Cyclic processes of valatile substances, coatings, removal of rings

Les réactions dans les gaz du four Les circuits de matières volutiles, croûtages, enlivement d'annemez

Von F. W. Locher, S. Sprung und D. Opitz, Forschungsinstitut der Zementindustrie, Düsseldorf

#### 1. Einleitung

1. Einleitung
Der Gosstrom im Zementofen, der dem Brenngutstrom
entgegenähaft, enthält außer Brenngutstaub im wesentlichen Alkall-, Schwefel-, Chlorid- und Fluoridverbindungen, die nus verdampten und dissoziferten Bestandtellen des Brennguts und des Brennstoffe durch Besktionvorwissend im Ofengas entstanden sind, Besgieren sie
mit dem Brenngut oder werden sie in den kälteren Bereichen des Ofena, im Vorwärmer oder in mebgeschalteten Trechnungsanlagen mit dem Brenngut niedergeschlagen, so bilden sie einen "inneren Kreislauf", Werden
sie dagugen in den Gustelnigungsanlagen niedergeschlagen, so bilden sie einen "inneren Kreislauf", Werden
sie dagugen in den Gustelnigungsanlagen hipsechleden
und dann dem Behateifigemisch wieder zugesetzt, so entsteht ein geschlossener "Justerer Kreislauf". Der füllere
Kreislauf ist unterbrochen, wenn ale mit dem abgeschiedenen Staub verwurfen oder mit dem Beingas smittiert
werden.

Durch die Kreisläufe werden die betreffenden Bestandbeile im Bremagut angereichert. Infolgedissen erblött sich auch ihre Konzentration im Zementklänker, im Grennfall auf den Wert, der sich nus der Zesammen-setzung des Robstoffgensisches ahne Verdampfungsver-luste errechnen libit. Die Anreicherung im Brenngut kann dessen Verhalten im Zementofen, insbesondere seine Haftfühigkeit und seine Schneilzeigenschaften, wessellich Haftibligkest und seine Echnelizeigenschaften, wesenlicht verändern und seint zur Bildung unerufnschter Azsätze beitragen. Außerdem ist sich mit einer unmittelbaren Resittlen zwischen den Bestandteilen des Ofengses und dem fasten Berengut zu rechnen, die ebenfalls Ansatz-uid Ringbildung hervorrufen kann.

Generalberoth Fuchteenim IV, VDZ-Rongres 'il Verfahrunatschnik der Zementberstelbung, rüsseldorf (2k. S. — 1. 10. 1972)

Die Resictionen im Ofengas sowie zwischen Ofengas und Brenngst beeinflussen in entscheidendem Maß auch die Emission gasfürmiger Verbindungen. Je größer der Anteil ist, der Infolge der Resktionen im Brenngul ver-bleibt, um so weniger wird emittiert.

bleibt, um so weniger wird emittiert.

Der vorliegende Bericht befaßt sich zusächst mit den Kreisläufen der Alkali-, Schwefel-, Chlorid- und Fluurid-verbindungen und geht daben zuch auf die Enlision dieser Stoffe ein. Im Anschluß denzu werden die Auswirkungen und den Ofenbetrich, Insbesondere ihre Bedeutung für die Anseiz- und Ringbildung behandelt sowie Mußnahmen zur Vermüchderung oder Beseitigung von Beiriebastörungen erüttert.

#### 2. Kreisläufe

2.1 Staub

2.1 S.t.a.u.b.

Der Staubgeheit der Ofengase spielt insbesondere dann eine entschaidende Rolle, wenn die Anreicharung der flächtigen Bestandreite im Ofen und im Vorwärmer durch Eingriffe in deres inneren und Rolleren Kreislauf vermindert werden soll. Der innere Kreislauf kann z. B. durch einen Gos-Beiguaß herabgesetzt werden, der den Vorwärmer umgeht und den obgesongten Teilstrom der Öfengases unmittelbur einer Essenderen Gaszelnigungsmäge zuführt. Die in dem Teilgasstrum ernhaltenen kondenserten flüchtigen Bestandteile werden zusammen mit dem Berungustsaub abgeschieden und anschließend obgeführt. Der Sußere Kreislauf kann dodurch unterbunden werden, daß der Staub, in dem die flöchtigen Bestandteile angereichert sind, nich Dorwänung des Ofengases durch den Vorwärmer und gegebetenfals durch die Treidnunge- oder Mahltrucknungsunlage abgeschieden und abgeführt wird.

ZEMENT-KAUK-GIPS -- Nr. 1/ 1872

1

Portland Cement Association



# Research and Development Information

5420 Old Orchard Road • Skokle, IL 60077-1083 • Fax (708) 966-978] • (708) 966-6200

PCA R&D Serial No. 1996

## Kiln Exit Build-Ups: Study of Alkali and Sulfur Volatilization

by Presbury B. West

© Portland Cement Association 1995

#### KILN EXIT BUILD-UPS: STUDY OF ALKALI AND SULFUR VOLATILIZATION

by

Presbury B. West\*

#### ABSTRACT

This report contains a bibliography of articles on cement kiln processes that affect the formation of kiln exit build-ups. Articles are included on the following topics: alkali, chlorine, and sulfur cycles, dust cycles, air blasters, by-pass systems, mathematical models of cyclic processes, and volatility of alkalies, chlorine, and sulfur. The citations came from a computer literature search and are supplemented with other references found in the PCA library. Many of the citations include either an abstract or a list of keywords.

Experimental work is reported on volatility of alkalies and sulfur from kiln feeds and 4th stage materials. Alkalies and sulfur are key components of kiln gases which react to form build-ups. Samples from three preheater and three precalciner kilns were studied. Volatility of alkalies and sulfur is usually less for 4th stage materials than for kiln feeds. Fourth stage materials from precalciners generally have lower alkali and sulfur volatility than similar materials from preheater kilns. It is concluded that increases of the sulfur-alkali molar ratio may cause the observed decreases in volatility. Potassium is more volatile than sodium for both kiln feeds and 4th stage materials. Addition of sulfates, changing the molar ratio of SO<sub>3</sub>-Na<sub>2</sub>O alkali equivalent to near 1.0, decreases the volatility of both sulfur and alkalies.

Thermal gravimetric experiments using kiln feeds indicated that calcination was not affected by the presence of 5% coal. Another series of experiments investigated the effect of oxygen on calcination; results were inconclusive. Future work is suggested on the effect of reducing conditions on volatilization, and testing models of cyclic phenomena in cement kilns.

Keywords: alkali bypass, alkali cycles, alkali volatility, cement manufacturing, kiln exit build-ups, portland cement, precalciners, preheaters, sulfur cycles, sulfur volatility.

#### SCOPE

This report describes the experiments performed and discusses the results of those experiments. In this project, the volatility of alkalies and sulfur was evaluated as well as the differences in their volatility between kiln feeds and fourth stage materials, because of their importance in modeling internal cycles in cement kilns. The differences of these same volatilities between preheater and precalciner kiln samples were also examined. The effect of reducing conditions and especially the presence of coal on the calcination of kiln feeds was the

## 3. Financial losses occurred due to kiln stops caused by clogging of cyclones

Period	1-st half 2008
Kiln output, t clnk/hour	152,92
Duration of kiln outage, hours	89,90
Clinker volume not produced due to outages, tonnes	13 747
Clinker purchased price, UAH/ton clnk	428,90
Clinker variable production cost, UAH/ton clnk	245,21
Cost of clinker replacement (purchase), UAH	2 525 275
Additional fuel consumption due to kiln outages, GJ	4 200
Fuel price, UAH/GJ	33,15
Additional fuel cost, UAH	139 237
Additional electricity consumption due to kiln outages, MWh	90
Electricity price, UAH/MWh	327,03
Additional electricity cost, UAH	29 433
Exchange rate, UAH/Euro <sup>1</sup>	7,655
Total cost (clinker replacement, additional fuel and electricity), UAH	2 693 944
Total cost (clinker replacement, additional fuel and electricity), Euro	351 910

<sup>&</sup>lt;sup>1</sup> National Bank of Ukraine, http://www.bank.gov.ua/ENGL/Fin\_mark/Kurs\_mid/kurs\_96-last.htm

Senior Scientist, Construction Technology Laboratories, Inc. (CTL) 5420 Old Orchard Road, Skokie, IL. 60077 (Phone 708-965-7500 x231, Fax 708-965-6541)